
Insulated-Touch Sensor Switch

Model: SR-8005














Feature


- Rated power: max.500W
- Sensor line to the maximum length : Max.≤15M.
- Can load HV-Halogen lamps, LED lamps, Electronic ballast
- Power on when press the LED light one time and power off when press the LED light again.
- Two sensor shell can be chosen.
- DC12-36V version is also available

Parameter


Part No.	luput Voltage	Current	Output	Remarks
SR-8005	100-240VAC	5A	500W	Detect touch to turn on/off
SR-8005-DC	12-36VDC	1x8A	1x(96-288)W	Detect touch to turn on/off

Product Size






Brief introduction of buttons



Wiring diagram



Safety & Warnings

- 1) The product shall be installed and serviced by a qualified person.
- 2) IP20. Please avoid the sun and rain. When installed outdoors, please ensure it is mounted in a water proof
- 3) Always be sure to mount this unit in an area with proper ventilation to avoid overheating.
- 4) Please check if the output voltage of any LED power supplies used comply with the working voltage of the
- 5) Never connect any cables while power is on and always assure correct connections to avoid short circuits before switching on.
- 6) Please ensure that the cable is secured tightly in the connector
- 7) For update information please consult your supplier.

Warranty Agreement

- 1) We provide lifelong technical assistance with this product:
- 5-year warranty. We print date on every products, for example :1125 means year 2011, week 25. The warranty is for free repair or replacement and covers manufacturing faults only.
- For faults beyond the 3-year warranty we reserve the right to charge for time and parts.
- 2) Limited Warrenty
- Any defects caused by wrong operation.
- Any damages caused by unauthorized removal, maintenance, modifying, incorrect connection and replacement of chips.
- Any damages due to transportation, vibration etc. after purchase.
- Any damages caused by earthquake, fire, lightning, pollution and abnormal voltage.
- Any damages caused by negligence, inappropriate storing at high temperatures and humidity or near harmful chemicals.
- Product has been updated
- 3) Repair or replacement as provided under this warranty is the exclusive remedy to the customer.